

INVOICE



Taylor Septic Services, LLC

810 Caspian Ct.
Deltona, Florida
386-878-6201

INVOICE NUMBER	23788
DATE	7/22/25
TERMS	FOB
SALESPERSON	
SHIPPED VIA	

Name _____

Address 22 Poinsettia Dr, Deland
inspection

QTY	UNIT	DESCRIPTION	TOTAL PRICE
		sectional septic tank side of house, one chamber no filter. Solids present, water level high. Lots of dirt in tank.	
		Bad drainfield tank deteriorating and 1/3 full of dirt old lid in tank.	
		Check # 185	
		SUB TOTAL	\$450.00
		TOTAL	

Comments:

Thank You



Pump out Inspection

Customer: _____ Date: 7/22/25

Address: 22 Poinsettia Pr

City: Deland

Tank Gallons: 900 Material: concrete Filter: Yes/No No Tank Depth: 1 1/2

Deflection device: Yes/No No Water level: Normal/High/Low High Pump Station: Yes/No No

Pump tank Gallons: _____ Material: _____ Tank Depth: _____

Alarm working: Yes/No No Pump working: Yes/No No Visual Defects: Yes/No No

Access lids: Good / Bad Risers Needed: Yes/No No Tank Location: Front / Back / Side

Drain field Location: Front / Back / Side

Defects:
Bad Drainfield, and
tank is 1/3 full of dirt
and old Broken lids.

Payment type: Cash / Credit / Check # _____

Customer Signature: _____ Date: 7/22/25

Inspected By: Brian Ruben

This inspection is not a warranty or guarantee of septic system past date of inspection because of unforeseeable use and events.